



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

14 NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Reno, NV) – At its meetings on April 8, 2009, the Nevada State Contractors Board adjudicated cases involving 14 contractors.

Capitol Overhead Door, Inc., license number 22971B (Overhead Doors) based out of Carson City, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the regulations of the Board and failure to keep in force a bond or cash deposit. The license was revoked.

J E Martensen Landscape Construction Co and Perfect Pavers, LLC., license numbers 59235 and 68063 (Landscaping and Masonry Limited To Pavers) based out of Sparks, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation; failure to keep in force a bond or cash deposit and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was ordered to pay administrative fines and post a bond. License 59235 is suspended.

Arley Ralph Poole, (Unlicensed) was found in violation of Nevada Revised Statute 624 for unlawful advertising. Poole was assessed an administrative fine.

Thomas Walker Dundas, (Unlicensed) was found in violation of Nevada Revised Statute 624 for contracting without a license.

Francis Frank Ford., (Unlicensed) was found in violation of Nevada Revised Statute 624 for contracting without a license. Ford paid an administrative fine.

Eclipse Property, LLC., license numbers 57025 and 61090 (Residential & Small Commercial and Prefabricated Steel Structures and Awnings & Louvres) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to comply with a written request from the Board; for the partnership, corporation, firm or association participating in a prohibited act; and failure to establish financial responsibility. The licensee was fined \$2,500 and ordered to pay investigative costs and ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

Bright Development, dba Bright Homes., license number 42564 (Residential & Small Commercial), based out of Modesto, CA, was found in violation of Nevada Revised Statute 624 for substandard workmanship. The licensee was ordered to pay the homeowner \$5,700.

Access Automated Door Systems, LLC, license number 56615 (Overhead Doors) based out of Sparks, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the terms of a construction project, thereby causing material injury to another; failure to respond to a written request from the Board; failure to include the Residential Recovery Fund information on a contract or proposal; failure to keep in force a bond or cash deposit; and failure to establish financial responsibility. The licensee was fined \$2,300; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Visions Concrete Design, LLC, license numbers 54796 and 54796A (Concrete Contracting), based out of Sparks, NV, was found in violation of Nevada Revised Statute 624 for abandonment of a construction project; failure to include the Residential Recovery Fund information on a contract or proposal; acting in the capacity of a contractor beyond the scope of the license; failure to pay money due for materials or services; failure to respond to a written request from the Board; failure to comply with an order from the Board; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$3,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

LeeDavid Emilio Conver, dba Jalumo Construction, license numbers 66521 and 57498 (Residential & Small Commercial and Carpentry, Remodeling & Repairs), based out of Winnemucca, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to comply with a written request from the Board; acting in the capacity of a contractor beyond the scope of the license; failure to keep in force a bond or cash deposit; failure to include the Residential Recovery Fund information on a contract or proposal; and for failure to notify the Board of a bankruptcy. The licenses were revoked.

Robert Wayne Buss, dba Wayne Buss Construction, license number 59438 (Residential & Small Commercial) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to comply with a written request from the Board. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Kenneth Eugene Peters, license number 64163 (Painting) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The licensee was fined \$1,500 and the license was revoked.

DLM Construction, Inc., license numbers 34562 and 70070 (Masonry, Installation of Non-Structural Brick Veneer & Stucco Stone and Lathing & Plastering) based out of Sparks, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500.

Lakemont Homes Nevada, Inc., license number 42420 (General Building), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to discharge a lien and failure to establish financial responsibility. The license was fined \$2,000 and ordered to release the liens on the homeowner and provide a current financial statement.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###