



NSCB News Release



FOR IMMEDIATE RELEASE
February 22, 2013

CONTACT: Jennifer Turner
Public Information Officer
(702) 486-1139

Scott Smith
Public Information Assistant
(702) 486-1165

NINE CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

HENDERSON, Nev. – At hearings conducted Feb. 6 in Reno and Feb. 21 in Henderson, the Nevada State Contractors Board took action against nine contractors for violations of Nevada Revised Statutes Chapter 624.

Do Rite Plumbing, Heating and Air Conditioning, Inc., license number 75933 (Plumbing, Heating Cooling Circulating Air, and Water Heaters), based out of Gardnerville, Nev., was found in violation of Nevada Revised Statute 624 for substandard workmanship; commencing work on a project without obtaining necessary building permits; allowing a license to be used by an unlicensed person; failure to include the monetary license limit on a contract or proposal; failure to include the Residential Recovery Fund information on a contract or proposal; failure to notify the Board of a change in personnel or address within 30 days of the change; and failure to establish financial responsibility. The licensee surrendered his license, was fined \$3,650 and ordered to pay investigative costs.

Alpine Steel, LLC, license number 42951 (Steel Reinforcing & Erection), based out of Las Vegas, Nev., was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was placed on a one year probation by the Board and is required to provide a new financial statement within 30 days, obtain a \$20,000 license bond within 10 days, submit bimonthly documentation that it remains current on payments to creditors, and pay investigative costs. The licensee's monetary limit was ordered to be reduced from \$2.5 million to \$1.7 million. All fines and costs must be paid within the timeframe established by the Hearing Officer or the license will be suspended.

-more-

Rise & Run, Inc., license number 46724 (Carpentry), based out of Las Vegas, Nev., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to establish financial responsibility. The Board ordered \$20,000 restitution be paid to the complainant. The licensee was fined \$600 and ordered to pay investigative costs. All fines and costs must be paid within the timeframe established by the Hearing Officer or the license will be suspended.

Bulldog Framing, license number 74171 (Carpentry), **H.C. Development, LLC**, license number 71064 (Residential and Small Commercial) and **Reliabuilt Construction Co., LLC**, license number 39858 (Residential and Small Commercial), all based out of Henderson, Nev., were found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was ordered to pay investigative costs. License number 74171 will be surrendered after the costs are paid. License numbers 71064 and 39858 will remain suspended until a new managing member and qualified individual are placed on the licenses.

Harvard Construction Co., Inc., license number 66500 (General Building), based out of Henderson, Nev., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to establish financial responsibility and willful disregard of the building laws of the state. The licensee was fined \$2,500 in fines and ordered to pay investigative costs. If the licensee does not provide a current financial statement and pay the fines and costs within the timeframe set by the Hearing Officer, the license will be revoked. The license is currently suspended.

A.L.S. Development and Management Corp., dba Paul Davis Restoration of Southern Nevada, license numbers 49038 (Residential and Small Commercial), 77072 (Carpentry), and 77073 (Painting and Decorating), and **A.L.S. Development and Management Corp., dba Dependable Construction**, license number 24161 (Residential and Small Commercial), all based out of Las Vegas, Nev., were found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to include the monetary license limit or license number on a contract

more-

or proposal. The licensee was fined \$500 and ordered to pay investigative costs. If the fines and costs are not paid within the timeframe set by the Hearing Officer, the license will be suspended.

Ted Mount, dba Natural Energy, license number 44635 (Solar Contracting), based out of Escondido, Calif., was found in violation of Nevada Revised Statute 624 for contracting on a suspended or revoked license and failure to include the Residential Recovery Fund information on a contract or proposal. The licensee was fined \$1,050 and ordered to pay investigative costs. If the fines and costs are not paid within the timeframe set by the Hearing Officer, the license will be suspended.

Bens Floor Covering, Inc., license number 37311A (Covering Floors and Carpet Laying), based out of Reno, Nev., was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to comply with a written request from the Board. The licensee was fined \$750 and ordered to pay investigative costs. The licensee must pay all fines and costs, make full restitution to damaged parties and reimburse the Board for any monies paid from the Residential Recovery Fund before future licensure will be considered. The license was revoked.

Floor Coating Creations, Ltd., license number 52883 (Painting), based out of Las Vegas, Nev., was found in violation of Nevada Revised Statute 624 for failure to keep in force a bond or cash deposit and failure to establish financial responsibility. The licensee was fined \$1,000 and ordered to pay investigative costs. Full restitution to damaged parties and reimbursement of the Board for any monies paid from the Residential Recovery fund must be paid prior to consideration of future licensure. The license was revoked.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

#

-more-

STAY CONNECTED

Visit our website: www.nscb.nv.gov

Join our social media network to receive current industry updates:

