



# NSCB News Release



**FOR IMMEDIATE RELEASE**

March 24, 2014

**CONTACT:** Jennifer Turner    Scott Smith  
Public Info. Officer    Public Info. Specialist  
(702) 486-1139    (702) 486-1165

## **CONTRACTORS DISCIPLINED BY BOARD ORDERED TO PAY \$8,100 IN FINES AND \$14,000 IN HOMEOWNER RESTITUTION**

**HENDERSON and RENO Nev.** –The Nevada State Contractors Board took action in its March 2014 Disciplinary Hearings against seven licensed contractors for violations of Nevada Revised Statutes Chapter 624.

**Intiaz Ahmed, dba Lobo Roofing**, license number 70178 (roofing) based out of Reno, Nev., was found in violation willful disregard of the safety or labor laws of the state, failure to include the Residential Recovery Fund information on a contract or proposal, and failure to include the monetary license limit or license number on a contract or proposal. The licensee was fined \$700 and ordered to pay investigative costs within 90 days or the license will be suspended.

**D N Roofing, Inc.**, license number 57056 (roofing), based out of Carson City, Nev., was found in violation for substandard workmanship, failure to take appropriate corrective action, failure to include the Residential Recovery Fund information on a contract or proposal, and failure to establish financial responsibility. The license was revoked. The licensee was fined \$1,600, ordered to pay investigative costs, make full restitution to all damaged parties, and reimburse the Board for any monies paid out of the Residential Recovery Fund prior to consideration of future licensure.

**Arrow Air Conditioning & Sheet Metal, LLC, dba Aire Serv of Las Vegas**, license number 53066 (refrigeration and air conditioning), based out of Henderson, Nev., was found in violation for willful disregard of the building laws of the state. The licensee was fined \$1,000, ordered to pay investigative costs, and pay restitution to the homeowner in the amount of \$500 within 30 days or the license will be suspended. The license limit was reduced to \$200,000 and the indemnitor on the license removed.

**Rise & Run, Inc.**, license number 46724 (carpentry), based out of Henderson, Nev., was found in violation for substandard workmanship and failure to establish financial responsibility. The licensee was fined \$500 and ordered to pay investigative costs and restitution in the amount of \$13,500 to the homeowner. The licensee

must provide the Board a current financial statement supporting the license limit within 30 days. If the financial statement fails to support the current monetary limit, the license limit will be reduced to the amount the financial statement supports. The license will be subject to suspension if fines, costs, and restitution are not paid in the time permitted by the Hearing Officer.

---

**Charles Owen Clark**, license number 71989 (finish carpentry), based out of Las Vegas, Nev., was found in violation for acting in the capacity of a contractor beyond the scope of the license, willful disregard of the building laws of the state, and failure to include the monetary license limit or license number on a contract or proposal. The license was revoked. The licensee was fined \$1,850, ordered to pay investigative costs, make full restitution to all damaged parties, and reimburse the Board for any monies paid out of the Residential Recovery Fund prior to consideration of future licensure.

---

**C. M. C. Mechanical, Inc.**, license number 73802 (refrigeration and air conditioning), based out of Las Vegas, Nev., was found in violation for contracting on a suspended or revoked license, failure to comply with a written request by the Board, failure to notify the Board of a change in personnel or address within 30 days of the change, failure to keep in force a bond or cash deposit, and failure to establish financial responsibility. The license was revoked. The licensee was fined \$2,100, ordered to pay investigative costs, make full restitution to all damaged parties, and reimburse the Board for any monies paid out of the Residential Recovery Fund prior to consideration of future licensure.

---

**Energypros Com, Inc.** license numbers 61315 (carpentry), 77929 (electrical contracting), and 78178 (refrigeration and air conditioning), based out of Las Vegas, Nev., was found in violation for advertising projects of construction beyond the scope of the license, failure to respond to a written request from the Board, and failure to establish financial responsibility. The license was revoked. The licensee was fined \$850, ordered to pay investigative costs, make full restitution to all damaged parties, and reimburse the Board for any monies paid out of the Residential Recovery Fund prior to consideration of future licensure.

---

**The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.**

---

# # #

**STAY CONNECTED**

Visit our website: [www.nscb.nv.gov](http://www.nscb.nv.gov)

Join our social media network to receive current industry updates: 