



Nevada State Contractors Board
NEWS RELEASE

www.nscb.state.nv.us

FOR IMMEDIATE RELEASE

Art Nadler,
Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION
AGAINST SIX CONTRACTORS**

(Reno, NV.) - At its meeting on Oct. 5, 2005, the Nevada State Contractors Board adjudicated cases involving six contractors.

Lynn House Moving., license number 51611 (Movement of Buildings) based out of Yerington, NV., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with Board's Notice to Correct; failure to cooperate in an investigation; two (2) counts aiding or abetting an unlicensed person; acting beyond the scope of the license; failure to notify owner of Residential Recovery Fund. The licensee was fined \$1,400.00 and assessed the cost of the investigation. The licensee was placed on Probation for one year, ordered to submit to a Business Review*, and ordered to reimburse the Residential Recovery Fund.

Erickson Roofing., license number 41776 (Roofing) based out of Reno, NV., was found in violation of Nevada Revised Statute 624 for failure to comply with the building laws regarding industrial insurance; failure to comply with the safety laws of the state; misrepresentation or omission of a material fact; failure to establish financial responsibility. The Board accepted the voluntary surrender the license.

American Concrete., license number 57980 (Concrete) based out of Reno, NV., was found in violation of Nevada Revised Statute 624 for substandard workmanship; acting beyond the scope of the license. The licensee was fined \$500 and assessed the cost of the investigation. The Licensee was ordered to hire a licensed C-18 contractor to complete the repairs within 30 days.

Custom Care, Inc., license number 56025 (Landscape) based out of Sparks, NV., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to include license number and monetary license limit on contract. Licensee was fined \$250.00; assessed the cost of the investigation; and ordered to pay restitution to the injured party in the amount of \$2,300.00. A one year Letter of Reprimand was placed on the licensee's files.

Gil Robison Construction & Development, license number 27770 (Residential & Small Commercial) based out of Reno, NV., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with the Board's Notice to Correct; failure to cooperate in an investigation; failure to notify the Board if any change occurs in the licensee's address or personnel; failure to include license number and monetary license limit on contract; failure to establish financial responsibility. The Board revoked the license of Gil Robison Construction & Development; ordered licensee to pay full restitution to all damaged parties; and assessed licensee the cost of the investigation, plus any expenses paid out by the Residential Recovery Fund.

Desert Roofing Inc., license number 47976 (Roofing) based out of Sparks, NV., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with the Board's Notice to Correct; failure to cooperate in an investigation; abandonment of a construction project; failure or refusal to comply with terms of a construction contract; failure to comply with a written request from the Board; failure to keep in force the bond or cash deposit; failure to establish financial responsibility. The Board revoked the license of Desert Roofing, Inc.; ordered licensee to pay full restitution to all damaged parties; and assessed licensee the cost of the investigation, plus any expenses paid out by the Residential Recovery Fund.

***The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.
