



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

CONTRACTORS BOARD TAKES DISCIPLINARY ACTION AGAINST SIX CONTRACTORS IN SOUTHERN NEVADA

(Henderson, NV) - At its meeting on July 25, 2007, the Nevada State Contractors Board adjudicated cases involving six contractors.

Floor Seasons, Inc., license number 54529 (Concrete Contracting), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship. The licensee paid the homeowner \$30,000 in restitution.

Won Shik Yun, dba Won Shik Yun, license numbers 43761 and 66844 (Pre-manufactured Housing, Residential & Small Commercial and Electrical Contracting) and ***Grand City Plumbing & Heating Co.***, license number 59122 (Plumbing & Heating), both based out of Las Vegas, NV, were found in violation of Nevada Revised Statute 624 for failure to include the monetary license limit or license number on a contract or proposal and failure to establish financial responsibility. The licensee was fined \$100 and ordered to pay restitution to the homeowner.

Vincent Francis Martano, dba Academy Enterprises, license number 52852 (Painting & Decorating) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; and failure to establish financial responsibility. The licensee was fined \$2,350 and ordered to investigate costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Meadow Valley Enterprises, LTD., license number 58843 (Landscaping) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; failure to establish financial responsibility; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit or license number on a contract or proposal; and failure to keep in force a bond or cash deposit. The licensee was fined \$3,200 and ordered to investigate costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

-- more --

Donald A. Schroeder, dba Don Schroeder, license number 23660B (Finish Carpentry) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; bidding or contracting for a construction contract in excess of the limit placed on the license; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit or license number on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$5,600 and ordered to investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

S&S Painting & Drywall, LLC, license number 53700 (Painting & Decorating), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for willful disregard of the laws of the State of Nevada regarding industrial insurance and failure to establish financial responsibility. The licensee was fined \$1,500 and ordered to investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###