



NSCB News Release



FOR IMMEDIATE RELEASE

November 16, 2012

CONTACT: Jennifer Turner Scott Smith
Public Info. Officer Public Info. Specialist
(702) 486-1139 (702) 486-1165

FOUR CONTRACTORS DISCIPLINED BY CONTRACTORS BOARD

HENDERSON Nev. –The Nevada State Contractors Board adjudicated cases involving four licensed contractors during its November 7 and 14 disciplinary hearings.

Ted Mount, owner, dba Natural Energy, license number 44635 (Solar Contracting), based out of Escondido, Calif., was found in violation of Nevada Revised Statute 624 for failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit or license number on a contract or proposal; contracting on a suspended or revoked license; failure to keep in force a bond or cash deposit; failure to establish financial responsibility; and acting in the capacity of a contractor beyond the scope of the license. The licensee was fined \$3,300, ordered to pay investigative costs, and provide the Board with a compiled financial statement prepared by a CPA. The license remains suspended. If fines and costs are not paid within the allocated timeframe set by the Hearing Officer, the license will be revoked.

Renovations of Las Vegas, Inc., license number 72107 (Residential and Small Construction), based out of Las Vegas, Nev., was found in violation of Nevada Revised Statute 624 for failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit or license number on a contract or proposal; failure to provide the name, license number, business address and telephone number of all subcontractors and persons who furnish material of \$500 or more for the project; and acting in the capacity of a contractor beyond the scope of the license. The licensee was fined \$850, ordered to pay investigative costs, and pull necessary building permits within a time set by the Hearing Officer. The license is subject to suspension if fines are not paid within the allocated timeframe set by the Hearing Officer.

Re-Bath of Las Vegas, LLC., license numbers 57470 (Glass and Glazing), 57471 (Plastic Tile and Wallboard) 69348 (Artificial or Cultured Marble) based out of Las Vegas, Nev., were suspended pending continuance of the hearing date for failure to establish financial responsibility.

Cree Concrete, LLC., license number 65492 (Concrete Contracting) based out of Las Vegas, Nev., was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to respond to a written

request from the Board; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit or license number on a contract or proposal; acting in the capacity of a contractor beyond the scope of the license; failure to comply with a written request by the Board; and failure to establish financial responsibility. The licensee was fined \$2,350 and ordered to pay investigative costs. The license was suspended, for up to 60 days, for licensee to provide the Board with a compiled financial statement supporting the license limit. If fines and costs are not paid within the allocated timeframe set by the Hearing Officer, the license will be revoked.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###

STAY CONNECTED

Visit our website: www.nscb.nv.gov

Join our social media network to receive current industry updates:

